


NOTES:

- (1) Three bearing trees have been marked with a 4" x 4" Aluminum Plate at each A.D.L. Brass Capped Monument indicated (BT) and marked BT- 1, 2, or 3
- (2) Witness Posts 4" x 4" x 4" painted white have been set or recovered at all Brass Capped Monuments and Recovered Secondary property corners and marked "Witness Post-Do Not Destroy-Lot (no) "
- (3) The natural meanders of the line of mean high water of Red Shirt Lake forms the seaward bounds of the lots adjoining the Lake. The corner monuments as established are witness corners, with the true corners being on the extension of the side lines and the above said natural meanders.
- (4) The section line easements which are to be vacated within this subdivision are those that bisect the platied 'tracts' only.

MONUMENT LEGEND

- ⊙ BLM Copperweid Monuments Recovered this Survey.
- ⊗ BLM -GLO Brass Cap Monuments Recovered this Survey.
- ⊕ Brass Cap Monuments Set this Survey.
- Aluminum Cap On 5/8" Rebar Set this Survey.
- ∠ Angle Point - No Monument Set.
- BT Three bearing trees taken this Survey.



TYPICAL MONUMENT MARKINGS